

---

**Download**



[Maplin UK Not Working Correctly During Tech Sale](#)

From: Julie Yarbrough <jy@emsv.com>  
Date: Mon May 3, 2004 12:19:35 am Europe/London  
To: [ems@inbox.demon.co.uk](mailto:ems@inbox.demon.co.uk)  
Subject: Re: Guido's Synthi AKS

The voltage is currently set for 110V, but there is a small front panel selector near the power cable so you can switch it quickly if you need be, without needing to get inside the unit.

I'm not sure about the reverb...if I remember correctly when Guido first mentioned that he thought it sounded quieter than the reverb on another AKS he used to have, and I took a quick look at the schematics at the time and thought it should be fairly easy to change that. I never really looked into it thoroughly, though, and he didn't send the unit back to me so I never really verified that. I'll have to take another look at the schematics, but my guess is that it shouldn't be much of a problem. From memory, the entire reverb circuit is pretty simple. I will try to look at the schematics in this regard, if I get a chance in the next few days. Unfortunately I'm rather in the middle of "panic mode" with one of my corporate design clients so I don't have a whole lot of time right at the moment.

I do also remember that this was a very, very nice unit in terms of the physical front panel and cosmetics, in beautiful condition.

Julie

-----  
Paul wrote:

Wow - thanks for the very detailed reply :) In addition do you know / recall if the input voltage was set at either 110V or 240V or was it switchable between the two? Also how about that quiet reverb issue that Guido has - is it indeed a simple fix? Many thanks, Paul

On Saturday, May 1, 2004, at 06:34 pm, Julie Yarbrough wrote:

Hello Paul,

I did both some repairs and some mods on the unit, listed below. These were done in late September/early October of last year:

-----  
Repairs

- Fixed broken wire causing no left output on left speaker
- Replaced faulty opamp in output circuit that was causing the right output to be noisier than the left
- Replaced a leaky capacitor in the envelope circuit that caused the envelope to not fully decay after being powered on for some time
- Cleaned scratchy pots
- Repaired broken wire inside the reverb tank output transducer that was causing there to be no reverb signal
- The keyboard functioned incorrectly and would repeat the lowest 16 notes when you were playing what should have been higher notes. Replaced bad IC in the DAC circuit inside the keyboard.
- Sequencer was completely non-functional. Replaced bad IC in sequencer clock circuit and replaced clock timing capacitor.
- Complete calibration as per service manual.

-----  
Modifications and upgrades done:

- Sync modification, oscillator 1 can be switchable to Sync to either Osc 2 or to Osc 3. There is an internal trimpot (accessible if you remove the back cover) which can adjust the amount of sync. Sync mod is pretty much exactly as described on Hinton's page, except I put the pot as a trimpot inside the unit instead of putting it on the front panel
- CV/Gate Mod with internal calibration trimpots: The gate mod is a slight alteration of that shown on Hinton's page. Unfortunately, there are some parts left off on the circuit shown in the webpage that could cause occasional problems in some units, so I have added those parts. Functionally, it performs the same way. On Guido's unit, one of the former Mic input jacks has been used as the Gate input jack, and the other Mic input jack has been used for the CV input. For the CV input, the circuitry used is similar to that shown on Hinton's page, but the implementation is different. The implementation used on Guido's unit does not go through the patch matrix and use up input #1. After discussion with Guido about the various ways I had implemented the mod for other people in the past, what I did was convert the Mic #2 input to a dedicated CV input. This CV input is wired directly to both Oscillators 1 and 2 (without going through the pin matrix) and so can be used independently of input #1 and without making any patches in the pin matrix. There are small internal trimpots (easy to get to by removing the main unit from its plastic case) that can be used to independently adjust the scaling of the CV to Osc 1 and to Osc 2 if need be.
- Filter switchable to 12dB/octave (toggle switch on front panel to switch from normal operation to 12dB/octave operation)
- Replaced 4 main filter capacitors with new, low leakage parts instead of ceramic disc caps
- Oscillator 1-2 main frequency capacitors replaced and upgraded
- Oscillator tracking trimpot replaced with multiturn trimpot instead of single turn, for better adjustment and stability

-----  
Hope this information helps.

Thanks,  
Julie

-----  
Paul wrote:

Hello Julie,

I am considering purchasing Guido's Synthi AKS and he's e-mailed me to let me know that you were the tech who overhauled the machine. He suggested you might not mind if I e-mail you to ask about the work involved.

I'd be really grateful if you could elaborate on the kinds of repairs / modifications you performed. Were they based on Graham Hinton's EMS modifications page? (<<http://www.hinton.demon.co.uk/ems/emsmods.html>> or <<http://www.hinton.demon.co.uk/ems/emsmods.html>>). If not please tell me more.

Guido's told me that the reverb is a bit quiet but that you've indicated this is an easy fix - is this the case? I would really appreciate your insight before I take the plunge so thanks for your time, I hope to hear back from you. Cheers, Paul

</blockquote></html>

---

[Maplin UK Not Working Correctly During Tech Sale](#)



---

While Maplin.co.uk isn't down today, the website reports it's having problems with server connections and.... can be downloaded from our website at [www.pwc.co.uk/maplin](http://www.pwc.co.uk/maplin) or you can ... of better-structured product ranges with a clearer technological focus ... A slimmed down Smart Home focussed version was rolled ... The fee structure incentivised Hilco to drive sales at competitive ... correct periods of occupation.. If we have a problem with your order, we'll get in contact through the details ... as soon as possible and give you the option of reordering at the correct price ... Discount codes cannot be stacked or applied to products already on sale or on offer. ... If you'd like to return your order, send us an email [help@maplin.co.uk](mailto:help@maplin.co.uk) and our ...

Website, [www.maplin.co.uk](http://www.maplin.co.uk). Maplin Electronics is an online retailer of electronic goods in the United Kingdom and Ireland, ... Sales received a boost when Maplin was invited to take prime advertising space in ... On 12 May 2018, operations in the centre at Brookfields were shut down after ... Bringing you the latest in Tech!. Avis de salariés chez Maplin Electronics Ltd à propos de la culture ... about the tech industry, the gadgets we sold and retail practice that hopefully will carry to other jobs. ... I have not worked there for a very long time but it was okay to work in. ... or electronics related issues, providing them with the correct components or ...

### [Marc by Marc Jacobs – Patchwork Cotton-Jersey T-Shirt](#)

The local maplin is shutting down today and they have a "full the bag for £5" promo running. If the item won't fit in the bag ask to have it included, my store just let .... 68 reviews from Maplin employees about Culture. ... Sales Assistant (Former Employee) – Clapham Junction, Greater London – 1 January 2020 ... Sometimes did not get the work life balance correct but tried. ... I loved it, the new tech, the helping people but mainly the team. without the team it would have been a different .... The future of electronics firm Maplin will be decided 'in a matter of days' after bosses put the ... Anxious wait for Chesterfield workers as Maplin goes up for sale ... He added: "They fundamentally believe the strategy is correct and that can win out. What is not working is the financial structure of the business.. Online shopping represents a huge amount of the UK's yearly spending, with over ... Any retailer should give you the opportunity to check your order and correct any ... You are within your rights to demand a refund for any goods that are faulty or ... According to the Consumer Rights Act, a retailer has to ensure that the sale is .... A free inside look at company reviews and salaries posted anonymously by employees. ... The pay is terrible respective to the amount of sales and troubleshooting knowledge you must have. ... If you're a tech geek, you'll enjoy that much. ... Pay your staff properly in accordance with their skill, knowledge and hard work, stop ... [Download Tentered v1.4.1 – Multi Purpose WordPress Theme](#)

From: Julie Yarbrough <jy@emsy.com>  
Date: Mon May 3, 2004 12:19:35 am Europe/London  
To: [emsy@inbox.demon.co.uk](mailto:emsy@inbox.demon.co.uk)  
Subject: Re: Guido's Synthi AKS

The voltage is currently set for 110V, but there is a small front panel selector near the power cable so you can switch it quickly if you need be, without needing to get inside the unit.

I'm not sure about the reverb...if I remember correctly when Guido first mentioned that he thought it sounded quieter than the reverb on another AKS he used to have, and I took a quick look at the schematics at the time and thought it should be fairly easy to change that. I never really looked into it thoroughly, though, and he didn't send the unit back to me so I never really verified that. I'll have to take another look at the schematics, but my guess is that it shouldn't be much of a problem. From memory, the entire reverb circuit is pretty simple. I will try to look at the schematics in this regard, if I get a chance in the next few days. Unfortunately I'm rather in the middle of "panic mode" with one of my corporate design clients so I don't have a whole lot of time right at the moment.

I do also remember that this was a very, very nice unit in terms of the physical front panel and cosmetics, in beautiful condition.

Julie

-----  
Paul wrote:

Wow - thanks for the very detailed reply :) In addition do you know / recall if the input voltage was set at either 110V or 240V or was it switchable between the two? Also how about that quiet reverb issue that Guido has - is it indeed a simple fix? Many thanks, Paul

On Saturday, May 1, 2004, at 06:34 pm, Julie Yarbrough wrote:

Hello Paul,

I did both some repairs and some mods on the unit, listed below. These were done in late September/early October of last year:

-----  
Repairs

- Fixed broken wire causing no left output on left speaker
- Replaced faulty opamp in output circuit that was causing the right output to be noisier than the left
- Replaced a leaky capacitor in the envelope circuit that caused the envelope to not fully decay after being powered on for some time
- Cleaned scratchy pots
- Repaired broken wire inside the reverb tank output transducer that was causing there to be no reverb signal
- The keyboard functioned incorrectly and would repeat the lowest 16 notes when you were playing what should have been higher notes. Replaced bad IC in the DAC circuit inside the keyboard.
- Sequencer was completely non-functional. Replaced bad IC in sequencer clock circuit and replaced clock timing capacitor.
- Complete calibration as per service manual.

-----  
Modifications and upgrades done:

- Sync modification, oscillator 1 can be switchable to Sync to either Osc 2 or to Osc 3. There is an internal trimpot (accessible if you remove the back cover) which can adjust the amount of sync. Sync mod is pretty much exactly as described on Hinton's page, except I put the pot as a trimpot inside the unit instead of putting it on the front panel.
- CV/Gate Mod with internal calibration trimpots: The gate mod is a slight alteration of that shown on Hinton's page. Unfortunately, there are some parts left off on the circuit shown in the webpage that could cause occasional problems in some units, so I have added those parts. Functionally, it performs the same way. On Guido's unit, one of the former Mic input jacks has been used as the Gate input jack, and the other Mic input jack has been used for the CV input. For the CV input, the circuitry used is similar to that shown on Hinton's page, but the implementation is different. The implementation used on Guido's unit does not go through the patch matrix and use up input #1. After discussion with Guido about the various ways I had implemented the mod for other people in the past, what I did was convert the Mic #2 input to a dedicated CV input. This CV input is wired directly to both Oscillators 1 and 2 (without going through the pin matrix) and so can be used independently of input #1 and without making any patches in the pin matrix. There are small internal trimpots (easy to get to by removing the main unit from it's plastic case) that can be used to independently adjust the scaling of the CV to Osc 1 and to Osc 2 if need be.
- Filter switchable to 12dB/octave (toggle switch on front panel to switch from normal operation to 12dB/octave operation)
- Replaced 4 main filter capacitors with new, low leakage parts instead of ceramic disc caps
- Oscillator 1-2 main frequency capacitors replaced and upgraded
- Oscillator tracking trimpot replaced with multiturn trimpot instead of single turn, for better adjustment and stability

-----  
Hope this information helps.

Thanks,  
Julie

-----  
Paul wrote:

Hello Julie,

I am considering purchasing Guido's Synthi AKS and he's e-mailed me to let me know that you were the tech who overhauled the machine. He suggested you might not mind if I e-mail you to ask about the work involved.

I'd be really grateful if you could elaborate on the kinds of repairs / modifications you performed. Were they based on Graham Hinton's EMS modifications page? (<<http://www.hinton.demon.co.uk/ems/emsmods.html>> or <<http://www.hinton.demon.co.uk/ems/emsmods.html>>). If not please tell me more.

Guido's told me that the reverb is a bit quiet but that you've indicated this is an easy fix - is this the case? I would really appreciate your insight before I take the plunge so thanks for your time, I hope to hear back from you. Cheers, Paul

</blockquote></html>

---

[Phoenix FD v3.1 For 3ds Max Free Download](#)

[Where Can I Download Showbox For Android](#)

Jobs could be at risk at Maplin in Kettering after the company entered administration. ... Maplin, one of the UK's biggest electronics retailers, collapsed after talks with potential buyers didn't result in a sale. ... Maplin employs about 2,500 people at its 200 stores, but it is not known how many work in Kettering. [Tenorshare ReiBoot Pro 8.0 Crack](#)

[Wondershare Registration Code And Licensed Email](#)

UK tat bazaar enters final death spiral ... Closing-down sale posters are being plastered over the shop windows of moribund Brit 'leccy tat .... This will record and store the footage from your cameras in a secure way, and ... you can have a professional come and ensure everything is working perfectly.. ... Waterloo Maplin store closing sale. Comment Gather round, those who think you could make a go of it in tech retail or are currently working in .... We're back online with a huge range of Smart Home, Security, Gaming, AV, Computing, STEM & more. ✓ Free Home Delivery.. Maplin is the UK's number one specialist technology retailer, with over 200 stores in ... great reputation for technological expertise and advice, the brand isn't typically the ... risks that might affect the deadline were properly identified and mitigated. ... an excellent 20% increase in sales during the first few months of opening.. Maplin's Tunbridge Wells branch is having a massive closing down sale in a ... The retailer, which has 2,300 employees across the UK, entered administration in the first ... in the Tunbridge Wells store having an up to 70 per cent off sale ... (PwC) after desperate attempts to save the tech chain fell through.. Maplin Employee Reviews for Store Manager ... Sometimes did not get the work life balance correct but tried. ... A large part of the day was developing and coaching the sales team in order to ... Enjoyable place for managers and tech heads.. Posted in NewsTagged Maplin, Maplin catalogue, radio shack, retail ... PoundLand has gone bankrupt since I visited England in June? ... It is a great shame that a chain of physical electronics shops that caters to hobbyists just isn't ... As sad as that may sound, and most likely correct it would be a great .... www.maplin.co.uk ... But according to the customer sales advisor "it doesn't have the correct sizes that you need" but sure ... What a brilliant store, it's got every tech gadget you'd ever wish to have. ... I have purchased a number of products from Maplin over the years, lots of faulty items, I sometimes get a refund after a long ... 3d2ef5c2b0 [Blackberry to launch its first Android Smartphone. Blackberry Priv in India on January 28](#)

3d2ef5c2b0

[FETO'nun finans kaynag na ag r darbe! Kaynak Holding yoneticilerine ag rlast r lm s muebbet!](#)